

Water pump replacement 65465 by 65467 requires change of camshaft pulley

Technical info no. 2110

Applies to manufacturer/model:

Volkswagen: Van T4

Applies to engines:

ACU, AEN, AET, AEU, APL, AVT

Applies to part no.:

No.	RUVILLE ref.	OE ref.
-----	--------------	---------

1.	65465	074121004
----	-------	-----------

2.	65467	074121005N
----	-------	------------

65465 / VW 074121004



Belt pulley, 18 teeth

65467 / VW 074121005N



Belt pulley, 20 teeth

Corresponding to the specifications of the vehicle manufacturer the following applies:

Only for vehicles with SI engine until YOM 29.02.2000.

When replacing the water pump with an 18 tooth belt pulley (65465) by the new 20 tooth profile (65467), the camshaft pulley must also be replaced. Original part number: 023 109 111 D

Additional installation information:

The toothed belt is difficult to mount.

Supplementary information:

Ruville recommends that all belt drive components be exchanged, when the belt-driven water pump is replaced.